

# Nixalite® Project Photos

## Protecting Endangered California Condors



**Problem:** California Condors sitting on microwave towers and eating the weather covers on the dish. Bad for both the Condors and the equipment.

**Solution:** Install Premium Nixalite Stainless Steel Bird Barrier Spikes. Always humane, proven effective.



### CALIFORNIA CONDOR (Gymnogyps californianus)



*Photo courtesy of the  
US National Park Service*

#### **Did you know..**

California Condors are the largest flying birds in North America. Their wingspan can reach more than 9 feet across!

**Status:** Endangered

**Population:** How many California Condors once lived is not known. In 1982, there were fewer than 25 Condors left in the wild. Today, their numbers have increased to about 200 and continue to rise.

**Threats:** Loss of habitat, shootings, pesticides and poisoning, encounters with utility equipment.

**Survival:** California condors can live up to 60 years old in the wild.

Unless specifically noted or listed as the property of another entity, the photographs, drawings and information shown on this page are copyrighted by Nixalite of America Inc - all rights reserved. Unauthorized copying, reprinting, or distribution is not allowed.



**Nixalite® of America Inc**  
1025 16th Ave, East Moline, IL. 61244  
Providing Superior Bird Control Since 1950

P: 800.624.1189 or 309.755.8771  
F: 800.624.1196 or 309.755.0077  
E: [birdcontrol@nixalite.com](mailto:birdcontrol@nixalite.com)  
[www.nixalite.com](http://www.nixalite.com)